



1/4





2/4





FIG. 2



3/4




FIG. 3





FIG. 4



**4/4**

$i=0$	$q$		$i=8$	$q$		$i=16$	$q$		$i=24$	$q$	
	8	16		...15	8	16	...23	8	16	8	16
$[13]$ [00]	$C_0$	$C_0$	$[33]$ [02]	$C_0$	$C_2$	$[31]$ [00]	$C_5$	$C_8$	$[11]$ [02]	$C_5$	$C_{10}$
$[12]$ [10]	$C_1$	$C_1$	$[32]$ [12]	$C_1$	$C_3$	$[30]$ [10]	$C_4$	$C_9$	$[10]$ [12]	$C_4$	$C_{11}$
$[11]$ [20]	$C_0$	$C_2$	$[31]$ [22]	$C_0$	$C_0$	$[33]$ [20]	$C_5$	$C_{10}$	$[13]$ [22]	$C_5$	$C_8$
$[10]$ [30]	$C_1$	$C_3$	$[30]$ [32]	$C_1$	$C_1$	$[32]$ [30]	$C_4$	$C_{11}$	$[12]$ [32]	$C_4$	$C_9$
$[03]$ [01]	$C_3$	$C_5$	$[23]$ [03]	$C_3$	$C_7$	$[21]$ [01]	$C_6$	$C_{13}$	$[01]$ [03]	$C_6$	$C_{15}$
$[02]$ [11]	$C_2$	$C_4$	$[22]$ [13]	$C_2$	$C_6$	$[20]$ [11]	$C_7$	$C_{12}$	$[00]$ [13]	$C_7$	$C_{14}$
$[01]$ [21]	$C_3$	$C_7$	$[21]$ [23]	$C_3$	$C_5$	$[23]$ [21]	$C_6$	$C_{15}$	$[03]$ [23]	$C_6$	$C_{13}$
$[00]$ [31]	$C_2$	$C_6$	$[20]$ [33]	$C_2$	$C_4$	$[22]$ [31]	$C_7$	$C_{14}$	$[02]$ [33]	$C_7$	$C_{12}$

**FIG. 5**